## HEADLIGHT CLEANER & COATING AGENT II Operating Procedures

## Headlight Cleaner & Coating Agent II



Check the headlight cracks or no cracks before starting work.

Wipe the headlight surface with a water-tightened chemical towel.

Cure with the masking tape before processing.



After shaking the
Headlight Cleaner
II well,apply it to a
paper cloth and apply it
all over.

After shaking the
Headlight
Cleaner II well,apply it
to a paper cloth and
apply it all over.

Spread on the entire headlight and leave for  $10\sim20$  minutes.

## Headlight Cleaner & Coating Agent II



Spread on the entire headlight and leave for 10~20 minutes.

Wipe off the liquid with the paper cloth.

Wipe the headlight surface with a watertightened chemical towel.



Apply the appropriate amount of headlight coat II to the non-woven fabric.



A proper amount evenly overcoating, let it sit for 3~5minutes and then wipe it dry with a dry towel.

Complete Image