







P02 Fluoropolymer Coating Operating Procedures

Substrate Treatment Iron Powder + Water Stain Removal

	<p>① Clean mud and oil stains on tires and wheels with a tire brush and sponge.</p>
	<p>② Remove insects with a super insect cleaner as need.</p>
	<p>③ Car wash by car wash machine or hand wash</p>
	<p>④ Use "Zara Clean" and horsehair brush to clean dirt such as the small parts of molding gaps.</p>
	<p>⑤ Remove Iron Powder with water or Zara Clean+Zeus</p>
	<p>⑥ Remove water stains with Clean X-7 or White Cleaner</p>

P02 Fluoropolymer Coating

	<p>⑦ Add water to the sponge to drain it or give a proper amount of water in the spray bottle (Workability Improvement)</p>
	<p>⑧ Apply an appropriate amount of Clean X Polymer to the sponge</p>
	<p>⑨ Apply liquid agent to the sponge and apply to body 50 cm square.</p>
	<p>⑩ When the applied over, remove water to the sponge.</p>
	<p>⑪ Drained with a sponge, trace the applied area 80% dry wipe.</p>
	<p>⑫ The remaining liquid, wipe dry with a chemical tower or special cloth.</p>