CLEAN X-POLYMER

Operating Procedures

Substrate Treatment Iron Powder+Water Stain Removal




Clean mud and oil stains on tires and wheels with a tire brush and sponge.

Remove insects with a super insect cleaner as need.



Hand wash or car wash machine.

Use 'Zara Clean'and horsehair brush to clean the dirt on small parts.



Remove water stains with CleanX-7 or White Cleaner.

Clean X-Polymer Coating



Add water to the sponge to drain it or give a proper amount of water in spray bottle. (Workability Improvement)

Apply an appropriate amount of Clean X Polymer to the sponge.



Apply liquid agent to the sponge and apply to body 50cm square.

When the coting finished,remove water on the sponge.

Drained with a sponge, trace the applied area 80% dry wipe.

The remaining liquid, wipe dry with a chemical tower or special cloth.